

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14


Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
1	Providing Rewinding of submersible pump sets with copper insulation wire suitable guage including opening and refitting after repair , removal of submersible pumpset and refixing in position at work site with all labour lead lift all equipments, transportation as per instructions of Engineer incharge of the work as per ISI Specification. with guarantee period of not less than 6 months Item Code 12.33 D						
	Sahyadri Lay out 3 rd Cross	1 ✓				1 ✓	
	Royal Enclave 3 rd Cross	1 ✓				1 ✓	
	MHR Layout 4 th Cross	1 ✓				1 ✓	
	Royal Enclave 2 nd Cross	1 ✓				1 ✓	
	Siddeshwara Lay out 3 rd Cross	1 ✓				1 ✓	
	NMHR Circle	1 ✓				1 ✓	
	Sidedahalli Circle	1 ✓				1 ✓	
	23 rd Cross Siddeshwara Lay out	1 ✓				1 ✓	
	27 th Cross Kirloskar Layout	1 ✓				1 ✓	
	Soundarya Layout 4 th Cross	1 ✓				1 ✓	
	Sidedahalli Govt School	1 ✓				1 ✓	
	Navy layout 5 th Cross	1 ✓				1 ✓	
	Soundarya Layout 1 st main 1 st Cross	1 ✓				1 ✓	
	25 th Cross Kirloskar layout	1 ✓				1 ✓	
						Present Qty 14.00	Job
						Payable Qty 14.00	Job

Assistant Engineer
Ward No-14

Asst. Executive Engineer
Dasarahalli Sub division


Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
2	Providing Rewinding of submersible pump sets with copper insulation wire suitable guage including opening and refitting after repair , removel of submersible pumpset and refixing in position at work site with all labour lead lift all equipments, transportation as per instructions of Engineer incharge of the work as per ISI Specification. with guarantee period of not less than 6 months Item Code 12.33 E						
	Navy Lay out 5 th Cross (Manjappa house)	1				1	
	Soundarya Lay out 1 st Main 1 st Cross	1				1	
	Soundarya Lay out 1 st Main 5 th Cross	1				1	
	Soundarya Lay out 1 st Main 7 th Cross	1				1	
	25 th Cross Kirloskar layout	1				1	
	Royal Enclave 3 rd Cross	1				1	
						Present Qty	6.00 Job
						Payable Qty	6.00 Job


 Assistant Engineer
 Ward No-14
 09/07/22
 to
 09/07/23


 Asst. Executive Engineer,
 Dasarahalli Sub division
 09/07/22


Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward						
Detailed measurement recorded on:						
Item No	Discription of Item	No	Length	Breadth	Depth	Qty
3	Providing Rewinding of submersible pump sets with copper insulation wire suitable guage including opening and refitting after repair , removal of submersible pumpset and refixing in position at work site with all labour lead lift all equipments, transportation as per instructions of Engineer incharge of the work as per ISI Specification. with guarantee period of not less than 6 months Item Code 12.33 F					
	Soundarya Lay out 1 st Main 9 th Cross	1				1
	Soundarya Lay out 2 nd Main 13 th Cross	1				1
	Soundarya Lay out 2 nd Main 6 th Cross	1				1
	Siddeshwara Lay out 2 nd Cross	1				1
	Balaji Lay out 3rd Main 14 th Cross	1				1
	Bhyraveshwara nagara 3 rd cross	1				1
	Sidedahalli Circle	1				1
	25 th cross Kirloskar layout	1				1
Present Qty						8.00
Payable Qty						8.00



 Assistant Engineer
 Ward No-14
 01/07/22
 to
 02/07/23

Asst. Executive En.
 Dasarahalli Sub-d
 01/07/2022
 03/07/2023

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14


Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
4	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (A)						
	Sahyadri Lay out 3 rd Cross	30				30	
	Royal Enclave 3 rd Cross	30				30	
	MHR Layout 4 th Cross	30				30	
	Navy layout 5 th cross	30				30	
	Kirloskar layout 27 th cross	30				30	
Present Qty						150	Each
Payable Qty						150	Each



 Assistant Engineer
 Ward No-14
 01/07/22
 to
 03/07/23


 Asst. Executive Engineer,
 Dasarahalli Sub division
 03/07/23

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14


Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
5	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (B)						
	Sahyadri Lay out 3 rd Cross	1				1	
	Royal Enclave 3 rd Cross	1				1	
	MHR Layout 4 th Cross	1				1	
	Royal Enclave 2 nd Cross	1				1	
	Siddeshwara Lay out 3 rd Cross	1				1	
Present Qty						5	Each
Payable Qty						5	Each



 Assistant Engineer
 Ward No-14
 01/07/22
 to
 03/07/22


 Asst. Executive Engineer,
 Dasarahalli Sub division
 03/07/2023

me of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:						
Discription of Item	No	Length	Breadth	Depth	Qty	Unit
Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 ©						
Navy Lay out 5 th Cross (Manjappa house)	30				30	
Soundarya Lay out 1 st Main 1 st Cross	30				30	
Soundarya Lay out 1 st Main 5 th Cross	30				30	
2 nd cross Siddeshwara layout	30				30	
MHR Circle	30				30	
Present Qty					150	Each
Payable Qty					150	Each


 Assistant Engineer
 Ward No-14
 01/07/21
 to
 03/12/23


 Asst. Executive Engineer,
 Dasarahalli Sub division
 03/12/23

**me of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward
No 14**


Detailed measurement recorded on:						
Discription of Item	No	Length	Breadth	Depth	Qty	Unit
Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (D)						
Soundarya Lay out 1 st Main 9 th Cross	30				30	
Soundarya Lay out 2 nd Main 13 th Cross	30				30	
Soundarya Lay out 2 nd Main 6 th Cross	30				30	
MHR Layout 4 th cross	30				30	
Siddeshwara layout 1 st main	30				30	
Present Qty					150	Each
Payable Qty					150	Each

[Signature]
Assistant Engineer
Ward No-14
01/04/12
03/07/12

[Signature]
Asst. Executive Engineer,
Dasarahalli Sub division
02/08/12

**Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward
No 14**

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
8	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (E)						
	Royal Enclave 2 nd Cross	1				1	
	Siddeshwara Lay out 3 rd Cross	1				1	
	NMHR Circle	1				1	
	Sidedahalli Circle	1				1	
	23 rd Cross Siddeshwara Lay out	1				1	
	27 th Cross Kirloskar Layout	1				1	
	Kirloskar layout 27 th cross	1				1	
	1 st main Soundarya layout	1				1	
						8	Each
						8	Each


 Assistant Engineer
 Ward No-14
 01/07/22
 to
 02/07/23


 Asst. Executive Engineer,
 Dasarahalli Sub division
 03/07/23

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:						
Discription of Item	No	Length	Breadth	Depth	Qty	Unit
Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code12.33.1 (F)						
Soundarya Lay out 1 st Main 9 th Cross	30				30.00	
Soundarya Lay out 2 nd Main 13 th Cross	30				30.00	
Soundarya Lay out 2 nd Main 6 th Cross	30				30.00	
4 th cross Soundarya layout	30				30.00	
2 nd main Soundarya layout	30				30.00	
Present Qty					150	Each
Payable Qty					150	Each


[Signature]
Assistant Engineer
Ward No-14

01/07/22
to
03/07/22

[Signature]
Asst. Executive Engineer,
Dasarahalli Sub division
03/07/22

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:							
	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
10	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (G)						
	Siddeshwara Lay out 3 rd Cross	1 ✓				1 ✓	
	NMH Circle	1 ✓				1 ✓	
	Sidedahalli Circle	1 ✓				1 ✓	
	23 rd Cross Siddeshwara Lay out	1 ✓				1 ✓	
	27 th Cross Kirloskar Layout	1 ✓				1 ✓	
	Soundarya Layout 4 th Cross	1 ✓				1 ✓	
	Kirloskar Layout 27 th cross	1 ✓				1 ✓	
	Bhoomika layout Ganesha Temple	1 ✓				1 ✓	
	2 nd main 6 th cross Soundarya layout	1 ✓				1 ✓	
	3 rd main kirloskar layout	1 ✓				1 ✓	
						Present Qty	Each
						Payable Qty	Each


 Assistant Engineer
 Ward No-14
 01/10/22
 03/10/22


 Asst. Executive Engineer,
 Dasarahalli Sub division
 02/10/22

ame of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No


Detailed measurement recorded on:						
Discription of Item	No	Length	Breadth	Depth	Qty	Unit
Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (H)						
Soundarya Lay out 1 st Main 9 th Cross	1				1	
Soundarya Lay out 2 nd Main 13 th Cross	1				1	
Soundarya Lay out 2 nd Main 6 th Cross	1				1	
Siddeshwara Lay out 2 nd Cross	1				1	
Balaji Lay out 3rd Main 14 th Cross	1				1	
Soundarya Layout 4 th Cross	1				1	
Sdedahalli school	1				1	
3 rd cross Bhyraveshwara nagara	1				1	
NMH Layout 5 th cross	1				1	
1 st cross royal enclave	1				1	
Present Qty					10	Each
Payable Qty					10	Each


Leaves
Assistant Engineer
Ward No-14
01/07/23
to
02/07/23

For the
Asst. Executive Engineer
Dasarahalli Sub division
03/08/23

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
12	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (I)						
	Soundarya Lay out 1 st Main 9 th Cross	1 ✓				1 ✓	
	Soundarya Lay out 2 nd Main 13 th Cross	1 ✓				1 ✓	
	Soundarya Lay out 2 nd Main 6 th Cross	1 ✓				1 ✓	
	Siddeshwara Lay out 2 nd Cross	1 ✓				1 ✓	
	Balaji Lay out 3rd Main 14 th Cross	1 ✓				1 ✓	
	Soundarya Layout 4 th Cross	1 ✓				1 ✓	
	Sdedahalli school	1 ✓				1 ✓	
	Sheshadri layout 3 rd cross	1 ✓				1 ✓	
	NMH circle	1 ✓				1 ✓	
	4 th cross Soundarya layout	1 ✓				1 ✓	
Present Qty						10 ✓	Each
Payable Qty						10 ✓	Each



 Assistant Engineer 01/07/22
 Ward No-14 02/07/22



 Asst. Executive Engineer,
 Dasarahalli Sub Division 02/07/22

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

14

Detailed measurement recorded on:						
Discription of Item	No	Length	Breadth	Depth	Qty	Unit
Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (J)						
Navy Lay out 5 th Cross (Manjappa house)	1				1	
Soundarya Lay out 1 st Main 1 st Cross	1				1	
Soundarya Lay out 1 st Main 5 th Cross	1				1	
Soundarya Lay out 1 st Main 7 th Cross	1				1	
Siddeshwara Lay out 2 nd Cross	1				1	
Balaji Lay out 3rd Main 14 th Cross	1				1	
Kirloskar layout 27 th cross	1				1	
3 rd cross Bhyraveshwara nagara	1				1	
2 main Meenakshi layout	1				1	
1 st cross royal enclave	1				1	
Present Qty					10	Each
Payable Qty					10	Each


 Assistant Engineer 01/07/22
 Ward No-14
 03/07/23


 Asst. Executive Engineer,
 Dasarahalli Sub division
 03/08/23

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14


Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
14	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (K)						
	Soundarya Lay out 1 st Main 9 th Cross	1				1.00	
	Soundarya Lay out 2 nd Main 13 th Cross	1				1.00	
	Soundarya Lay out 2 nd Main 6 th Cross	1				1.00	
	27 th cross kirloskar layout	1				1.00	
	Kirloskar layout 25 th cross	1				1.00	
						Present Qty	5.00 Each
						Payable Qty	5.00 Each


Assistant Engineer
Ward No-14
01/07/22
02/07/22

Asst. Executive Engineer,
Dasarahalli Sub division
01/07/22

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14


Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
15	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (L)						
	Navy Lay out 5 th Cross (Manjappa house)	30				30	
	Soundarya Lay out 1 st Main 1 st Cross	30				30	
	Soundarya Lay out 1 st Main 5 th Cross	30				30	
	4 th cross Soundarya layout	30				30	
	Sheshadri Layout 3 rd cross	30				30	
						Present Qty	150 Each
						Payable Qty	150 Each



 Assistant Engineer
 Ward No-14
 01/07/12
 03/07/13


 Asst. Executive Engineer,
 Dasarahalli Sub Division
 03/07/12

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
16	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (M)						
	Sidedahalli Circle	1				1.00	✓
	23 rd Cross Siddeshwara Lay out	1				1.00	✓
	27 th Cross Kirloskar Layout	1				1.00	✓
	Siddeshwara layout 3 rd cross	1				1.00	✓
	Bhoomika layout Ganesha temple	1				1.00	✓
Present Qty						5.00	Each
Payable Qty						5.00	Each


 Assistant Engineer
 Ward No-14
 01/07/22
 to
 03/07/23


 Asst. Executive Engineer,
 Dasarahalli Subdivision
 03/07/23

**Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No
14**

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
17	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (N)						
	Sahyadri Lay out 3 rd Cross	1				1	
	Royal Enclave 3 rd Cross	1				1	
	MHR Layout 4 th Cross	1				1	
	Royal Enclave 2 nd Cross	1				1	
	Siddeshwara Lay out 3 rd Cross	1				1	
	NMHR Circle	1				1	
	Sidedahalli Govt School	1				1	
	Balaji layout 3 rd cross	1				1	
	3 rd cross Bhyraveshwara nagara	1				1	
	1 st cross Soundarya layout	1				1	
Present Qty						10	Each
Payable Qty						10	Each

[Signature]
Assistant Engineer
Ward No-14
01/07/13

[Signature]
Asst. Executive Engineer,
Dasarahalli Sub division
03/08/2013

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:


Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
18	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (O)						
	Navy Lay out 5 th Cross (Manjappa house)	1				1	
	Soundarya Lay out 1 st Main 1 st Cross	1				1	
	Soundarya Lay out 1 st Main 5 th Cross	1				1	
	Soundarya Lay out 1 st Main 7 th Cross	1				1	
	Siddeshwara Lay out 2 nd Cross	1				1	
	Balaji Lay out 3rd Main 14 th Cross	1				1	
	Sahyadri layout 3 rd Cross	1				1	
	MHR Circle	1				1	
	2 nd main 13 th cross Soundarya layout	1				1	
	3 rd cross Bhyraveswaranagara	1				1	
Present Qty						10	Each
Payable Qty						10	Each


Assistant Engineer
Ward No-14
01/07/23
to
03/07/23

Asst. Executive Engineer,
Dasarahalli Sub division
03/07/23

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14


Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
19	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (P)						
	Soundarya Lay out 1 st Main 9 th Cross	1				1	
	Soundarya Lay out 2 nd Main 13 th Cross	1				1	
	Soundarya Lay out 2 nd Main 6 th Cross	1				1	
	2 nd main Balaji layout	1				1	
	2 nd cross Siddeshwara layout	1				1	
						Present Qty	5 Each
						Payable Qty	5 Each



 Assistant Engineer
 Ward No-14
 01/07/22
 to
 02/10/23


 Asst. Executive Engineer,
 Dasarahalli Sub division
 02/10/23

Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No 14

Detailed measurement recorded on:							
No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
20	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (Q)						
	Navy Lay out 5 th Cross (Manjappa house)	1				1	✓
	Soundarya Lay out 1 st Main 1 st Cross	1				1	✓
	Soundarya Lay out 1 st Main 5 th Cross	1				1	✓
	4 th Cross Soundarya lay out	1				1	✓
	27 th cross kirloskar layout	1				1	✓
Present Qty						5	✓ Each
Payable Qty						5	✓ Each


 Assistant Engineer
 Ward No-14
 01/07/22
 02/07/22


 Asst. Executive Engineer,
 Dasarahalli Sub division
 02/07/22

**Name of Work ; Maintaanance and Repairs of Bore wells in Bagalagunte Ward No
14**

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
21	Replacing of pump parts.The following main parts of submersible pumpsets requiring replacements as per ISI specification with guarantee period of not less than 12 months Item Code 12.33.1 (R)						
	Sahyadri Lay out 3 rd Cross	1				1	
	Royal Enclave 3 rd Cross	1				1	
	MHR Layout 4 th Cross	1				1	
	Sidedahall Govt School	1				1	
	Bhoomika layout 2 nd Cross	1				1	
						Present Qty	5 Each
						Payable Qty	5 Each

[Signature]
Assistant Engineer
Ward No-14
01/07/23
03/07/23

[Signature]
Asst. Executive Engineer,
Dasarahalli Sub division
03/07/23

**Name of Work ; Maintaanance of Bore well in Ward No 14 Bagalagunte ,
Dasarahalli Sub division**

Detailed measurement recorded on:							
Discription of Item	No	Length	Breadth	Depth	Qty	Unit	
Providing and Replacing of Rotor, as per ISI Specification with guarantee period of not less than 12 months Item Code 12.33.3(D)							
Royal Enclave 2 nd Cross	1 ✓				1 ✓		
Siddeshwara Lay out 3 rd Cross	1 ✓				1 ✓		
NMH Circle	1 ✓				1 ✓		
Sidedahalli Govt School	1 ✓				1 ✓		
23 rd Cross Siddeshwara Lay out	1 ✓				1 ✓		
27 th Cross Kirloskar Layout	1 ✓				1 ✓		
25 th cross Kirloskar layout	1 ✓				1 ✓		
2 nd main 13 th cross Balaji layout	1 ✓				1 ✓		
2 nd main Meenakshi layout	1 ✓				1 ✓		
Sahyadri layout 3 rd cross	1 ✓				1 ✓		
Present Qty					10	Each	
Payable Qty					10	Each	

[Signature]
Assistant Engineer
Ward No-14
01/07/12
to
03/07/13

[Signature]
Asst. Executive Engineer,
Dasarahalli Sub division
03/08/12

**Name of Work ; Maintaanance of Bore well in Ward No 14 Bagalagunte ,
Dasarahalli Sub division**

Detailed measurement recorded on:							
Item No	Discription of Item	No	Length	Breadth	Depth	Qty	Unit
23	Providing and Replacing of Rotor, as per ISI Specification with guarantee period of not less than 12 months Item Code 12.33.3 (E)						
	Navy Lay out 5 th Cross (Manjappa house)	1				1	
	Soundarya Lay out 1 st Main 1 st Cross	1				1	
	Soundarya Lay out 1 st Main 5 th Cross	1				1	
	Soundarya Lay out 1 st Main 7 th Cross	1				1	
	Siddeshwara Lay out 2 nd Cross	1				1	
	Balaji Lay out 3rd Main 14 th Cross	1				1	
	Bhoomiha layout Ganesha temple	1				1	
	3 rd main (near Mudlegowda house)	1				1	
	1 st cross Royal enclave	1				1	
	3 rd Cross Siddeshwara layout	1				1	
Present Qty						10	Each
Payable Qty						10	Each

[Signature]
Assistant Engineer
Ward No-14
09/10/23

[Signature]
Asst. Executive Engineer,
Dasarahalli Sub division
03/10/23